
# Расход и скорость цилиндров

## Пневматические и электропневматические распределители

#### Схема измерения расхода.



## Максимальная скорость (без нагрузки), достигаемая комбинацией определенных дросселей и цилиндра (мм/с)

Мод.	32	40	50	63	80	100	125
GSCU-1/8"; GSVU-1/8"; GMCU-1/8"; GSCU-1/8"	1000	954	611	385	239	153	183
GSCU-1/4"; GSVU-1/4"; GMCU-1/4"; GSCU-1/4"	-	1000	1000	719	446	285	-
RFU 452 M5	246	-	-	-	-	-	-
RFU 482-1/8"	259	166	106	67	41	-	-
RFU 483-1/8"	638	408	261	165	102	65	-
RFU 444-1/4"	-	709	454	286	177	114	73
RFU 446-1/4"	-	-	972	612	380	243	155
SCU M5 - SVU M5	213	-	-	-	-	-	-
SCU-1/4"; SVU-1/4"; MCU-1/4"; MVU-1/4"	-	1000	734	462	287	183	117
SCU-1/8"; SVU-1/8"; MCU-1/8"; MVU-1/8"	557	356	228	144	89	57	-
SCU-3/8"; MCU-3/8"	-	-	-	773	479	307	196
SCU-1/2"; MCU-1/2"	-	-	-	-	1000	1000	-

### Для достижения вышеуказанных скоростей присоединяемая трубка должна иметь определенный диаметр и не превышать (если указано) максимальную длину (мм)

6/4 max 4000	6/4 max 1000	6/4 max 1000	8/6	8/6	6/4 max 1000	-
-	6/4 max 1000	8/6 max 4500	8/6 max 3500	8/6 max 3500	8/6 max 3500	8/6 max 3500
4/2 max 3000	-	-	-	-	-	-
4/2 max 3000	4/2 max 3000	4/2 max 2500	4/2 max 2500	4/2 max 2500	-	-
6/4 max 8000	6/4 max 8000	6/4 max 8000	6/4 max 8000	6/4 max 8000	6/4 max 8000	-
-	6/4 max 3000	6/4 max 3000	6/4 max 3000	6/4 max 3000	6/4 max 3000	6/4 max 3500
-	-	8/6 max 4500	8/6 max 4000	8/6 max 4000	8/6 max 4000	8/6 max 4000
4/2 max 4000	-	-	-	-	-	-
-	6/4 max 1000	8/6 max 8000	8/6 max 8000	8/6 max 8000	8/6 max 8000	8/6 max 8000
6/4	6/4	6/4	6/4	4/2 max 2500	4/2 max 2500	-
-	-	-	8/6 max 3000	8/6 max 3000	8/6 max 3000	8/6 max 3000
-	-	-	-	10/8	12/10 max 250	-
	- 4/2 max 3000 4/2 max 3000 6/4 max 8000 - - 4/2 max 4000 - 6/4 -	-     6/4 max 1000       4/2 max 3000     -       4/2 max 3000     4/2 max 3000       6/4 max 8000     6/4 max 8000       -     6/4 max 3000       -     6/4 max 3000       -     6/4 max 1000       -     6/4 max 1000       6/4     6/4 max 1000       6/4     6/4	-     6/4 max 1000     8/6 max 4500       4/2 max 3000     -     -       4/2 max 3000     4/2 max 3000     4/2 max 2500       6/4 max 3000     6/4 max 3000     6/4 max 3000       -     6/4 max 3000     6/4 max 3000       -     8/6 max 4500     -       4/2 max 4000     -     -       -     6/4 max 1000     8/6 max 4500       4/2 max 4000     -     -       -     6/4 max 1000     8/6 max 8000       6/4     6/4     6/4       6/4     6/4     6/4	-     6/4 max 1000     8/6 max 4500     8/6 max 3500       4/2 max 3000     -     -     -       4/2 max 3000     4/2 max 3000     4/2 max 2500     4/2 max 2500       6/4 max 3000     6/4 max 8000     6/4 max 8000     6/4 max 8000       6/4 max 8000     6/4 max 3000     6/4 max 3000     6/4 max 3000       -     6/4 max 3000     6/4 max 3000     6/4 max 3000       -     -     8/6 max 4500     8/6 max 4000       -     -     -     -       -     6/4 max 1000     8/6 max 8000     8/6 max 8000       6/4     6/4     6/4     6/4       -     -     -     -	-     6/4 max 1000     8/6 max 4500     8/6 max 3500     8/6 max 3500       4/2 max 3000     -     -     -     -       4/2 max 3000     4/2 max 3000     4/2 max 2500     4/2 max 2500     4/2 max 2500       6/4 max 8000       -     6/4 max 3000     6/4 max 3000     6/4 max 3000     6/4 max 3000       -     6/4 max 3000     6/4 max 3000     6/4 max 3000     6/4 max 3000       -     -     -     -     -     -       -     6/4 max 1000     8/6 max 8000     8/6 max 8000     8/6 max 8000       4/2 max 1000     -     -     -     -       -     -     -     -     -       -     6/4 max 1000     8/6 max 8000     8/6 max 8000     8/6 max 8000       6/4     6/4     6/4     4/2 max 2500     -       -     -     -     -     -  -     -     -     -     -     -  -     6/4 <t< td=""><td>-     6/4 max 1000     8/6 max 4500     8/6 max 3500     8/6 max 3500     8/6 max 3500       4/2 max 3000     -     -     -     -     -     -       4/2 max 3000     4/2 max 3000     4/2 max 3000     4/2 max 2500     4/2 max 2500     -       6/4 max 8000       -     6/4 max 3000       -     6/4 max 3000       -     -     -     -     -     -     -       -     6/4 max 1000     8/6 max 4500     8/6 max 4000     8/6 max 4000     8/6 max 8000       4/2 max 4000     -     -     -     -     -       -     -     -     -     -     -       -     -     -     -     -     -       -     6/4 max 1000     8/6 max 8000     8/6 max 8000     8/6 max 8000     8/6 max 8000</td></t<>	-     6/4 max 1000     8/6 max 4500     8/6 max 3500     8/6 max 3500     8/6 max 3500       4/2 max 3000     -     -     -     -     -     -       4/2 max 3000     4/2 max 3000     4/2 max 3000     4/2 max 2500     4/2 max 2500     -       6/4 max 8000       -     6/4 max 3000       -     6/4 max 3000       -     -     -     -     -     -     -       -     6/4 max 1000     8/6 max 4500     8/6 max 4000     8/6 max 4000     8/6 max 8000       4/2 max 4000     -     -     -     -     -       -     -     -     -     -     -       -     -     -     -     -     -       -     6/4 max 1000     8/6 max 8000     8/6 max 8000     8/6 max 8000     8/6 max 8000

Расход воздуха распределите	ля, необхо,	димый для	достижени	я вышеука	занных ско	оростей (Нл	1/мин)	
GSCU-1/8"; GSVU-1/8"; GMCU-1/8"; GSCU-1/8"	337,61	503,25	503,62	503,80	504,31	504,44	-	
GSCU-1/4"; GSVU-1/4"; GMCU-1/4"; GSCU-1/4"	-	527,52	824,25	940,87	941,10	939,65	942,74	
RFU 452 M5	83,05	-	-	-	-	-	-	
RFU 482-1/8"	87,44	87,57	87,37	87,67	86,51	-	-	
RFU 483-1/8"	215,40	215,23	215,13	215,92	215,23	214,31	-	
RFU 444-1/4"	-	374,01	374,21	374,25	373,48	375,86	376,06	
RFU 446-1/4"	-	-	801,17	800,85	801,83	801,17	798,49	
SCU M5 - SVU M5	71,91	-	-	-	-	-	-	
SCU-1/4"; SVU-1/4"; MCU-1/4"; MVU-1/4"	-	527,52	605,00	604,56	605,59	603,35	602,73	
SCU-1/8"; SVU-1/8"; MCU-1/8"; MVU-1/8"	188,05	187,80	187,93	188,44	187,80	187,93	-	
SCU-3/8"; MCU-3/8"	-	-	-	1011,53	1010,73	1012,18	1009,71	
SCU-1/2"; MCU-1/2"	-	-	-	-	2110,08	3297,00	-	
Объемы, достигаемые при использовании цилиндров с ходом 1000 мм и давлении 6 бар								